



PRODUCT DATA SHEET

FORMULA FIVE® Mold Sealer-S (Super)

General Product Information

FORMULA FIVE® Mold Sealer-S (Super) is a premium high durability semi-permanent base coat designed for use on most mold or plug substrates including composite (FRP/GRP¹), glass, aluminum and steel. Seals the mold surface and fills micro-porosity to create a smooth high gloss surface. Recommended for most molding processes including contact molding, hand lay up, spray up, cast polymer and closed molding. Particularly recommended for use in new composite mold initialization, sealing reconditioned or repaired areas of previously seasoned molds, and as a base coat to optimize the performance of semi-permanent top coats. Also recommended as a mold sealer with sacrificial mold release systems such as wax, polymeric, spray or wipe on slip coat mold releases. Simple wipe on leave on application. Recommended application temperature is 70°F (21°C); do not apply to hot molds over 350°F (177°C). Suitable for molding process temperatures up to 500°F (260°C).

NOTE: The cross-linking resins used in FORMULA FIVE® Mold Sealer-S cure by hydrolysis (interaction with moisture in the atmosphere) and temperature. Recommended storage is in original containers tightly sealed avoiding extreme temperatures. Decant the amount of material expected to be used into HDPE with a positive closure just before use. Do not return air exposed release back into original container.

¹ FRP/GRP = Fiber Reinforced Polymer or Plastic / Glass Reinforced Plastic or Polyester

Preparing Mold Surface

FORMULA FIVE® Mold Sealer-S is ready to use as received - do not stir or mix. Must be applied to a clean surface to perform properly. Clean mold thoroughly with FORMULA FIVE® Mold Cleaner according to instructions or, if necessary, by compounding followed by warm water/detergent wash and followed by FORMULA FIVE® Mold Cleaner. If release agents containing wax or silicone have previously been used on the mold, apply FORMULA FIVE® Wax Stripper according to instructions. Polish to desired level of gloss prior to application of FORMULA FIVE® Mold Sealer-S. Use tape test² at several places on molding surface to verify cleanliness.

² Use good quality 3/4 or 1 inch (18-24 mm) wide general-purpose making tape such as Scotch® Performance Masking Tape 234. Always use the same tape so the feel of its standard removal becomes familiar. Apply a piece of tape about 8" (20 cm) in length and burnish to the mold. Pull the tape up at a 90-degree angle to the surface. You should hear a zipping sound and feel resistance as tape peels off of mold surface if mold is clean. When testing a mold surface that has properly applied mold release, very little resistance should be felt. Perform tape test at different areas of mold to ensure cleanliness or proper mold release application.

Directions for Use

Consult Material Safety Data Sheet (MSDS) prior to use. FORMULA FIVE® Mold Sealer-S should always be used in a well-ventilated area with appropriate personal protection equipment, including solvent resistant gloves and eye protection.

Using a clean dry lint-free cloth or high quality paper towel, wet but not dripping with FORMULA FIVE® Mold Sealer-S, gently wipe mold surface covering up to 5 ft² (0.5 m²) at a time. Do not re-use cloths after drying as they will be contaminated with partially cured polymers that will cause streaking. Never pour mold sealer directly on mold. Reapply mold sealer to cloth frequently during application.

Observe area just treated with FORMULA FIVE® Mold Sealer-S, waiting approximately 20-60 seconds. Just before carrier solvent flashes off (becomes dry) lightly dust wipe or fly-wipe to redistribute the polymer. Do not wipe hard or wipe totally dry and do not polish at this point. The wipe-off step is essential to help the sealer cure evenly with reduced haze or streaking. If minor streaking remains after last coat is dry use a clean and dry microfiber cloth to polish lightly.

Repeat on neighboring areas, overlapping to ensure complete coverage, until mold surface is completely covered. After solvent carrier dries allow 20 minutes for mold sealer to cure. Apply one additional coat of FORMULA FIVE® Mold Sealer-S following the same procedure and allow 30 minutes final cure time before applying FORMULA FIVE® Glossy Top Coat, FORMULA FIVE® Matte Top Coat, or other mold releases. Best practice for new, reconditioned or repaired areas of previously seasoned molds is to apply 3 coats of mold sealer, allowing 30 minutes cure time for each coat and a final cure time of 60 minutes or overnight.

FORMULA FIVE® Mold Sealer-S will outperform most mold sealers when applied at ambient temperatures. It will perform very well at application temperatures of 70°F (21°C) and above, but curing by heating at temperatures above process or part resin exotherm temperature makes a more durable release base coating. Longer curing times between mold sealer coats and for final cure will also make a more durable base.

Spray application may be used with FORMULA FIVE® Mold Sealer-S. Spray in thin coats; wipe-off is still required following the procedures above to reduce hazing or streaking.

1 GALLON (3.79 LITER) JERRICAN

REXCO • P.O. Box 80996 • Conyers, GA 30013 • U.S.A.
Telephone (770) 483-7610 • Fax (770) 483-8550 • Toll Free (800) 888-1060 (U.S.A. and Canada)
E-mail: info@rexco-usa.com Website: www.rexco-usa.com

DISCLAIMER: The information and recommendations contained herein are, to the best of our knowledge, accurate and reliable. No guarantee of their accuracy is made, however, and the products discussed are sold without warranty, express or implied, and upon condition that purchasers shall make their own tests to determine the suitability of such products for their particular purposes and uses.